

## Air-Conditioning Compressor for Electronic Vehicle

### Air Conditioning Pump For BYD Qin/E6



<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003010
<b>Product Specification</b>	(ACE66D)BC28B; HDE-8103020D; High Voltage:DC-408.8V
<b>Application</b>	BYD(Qin/E6)

### Air Conditioning Pump For Haili (Emgrand EV450)



<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003031
<b>Product Specification</b>	ETS34QVBGAA; High Voltage:DC-330V
<b>Application</b>	Haili (Emgrand EV450)

### Air Conditioning Pump For BYD E6



<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003012
<b>Product Specification</b>	(ACD26B)BC28B; MEEY-8103020; High Voltage:DC-531.2V
<b>Application</b>	BYD (E6)

## Air-Conditioning Compressor for Electronic Vehicle

### Air Conditioning Pump For Emgrand EV300



<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003023
<b>Product Specification</b>	EVS34QVBEEA-6BF; High Voltage:DC-330V
<b>Application</b>	Emgrand (EV300)

### Air Conditioning Pump For BYD Qin DM-I



<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003043
<b>Product Specification</b>	HA2HE-8103020; High Voltage:320V
<b>Application</b>	BYD (Qin DM-I)


### Air Conditioning Pump For SAIC Maxus EV80



<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003007
<b>Product Specification</b>	SANDEN_SHS-33H4167; High Voltage:DC-330V
<b>Application</b>	SAIC Maxus EV80

## Air-Conditioning Compressor for Electronic Vehicle

### Air Conditioning Pump For Haili (BAIC EU5)




<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003040
<b>Product Specification</b>	E00110188; High Voltage: DC-330V
<b>Application</b>	Haili (BAIC EU5)

### Air Conditioning Pump For DENSO (GAC AION S)



<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003075
<b>Product Specification</b>	ESB34C; High Voltage: DC-330V
<b>Application</b>	DENSO (GAC AION S)

### Air Conditioning Pump For Sanden (Volvo S90)



<b>Product Type</b>	Air Conditioning Pump - Remanufactured
<b>Product No.</b>	8005003131
<b>Product Specification</b>	SHS-33H3167; High Voltage: DC-330V
<b>Application</b>	Sanden (Volvo S90)

## The Instrument Cluster LCD Display

### LCD Navigation Display For Chrysler



<b>Model Number</b>	SA1336
<b>Application</b>	Car Navigation
<b>Model</b>	Chrysler, Dodge RAM, Jeep Renegade Radio Navigation
<b>Part No.</b>	LA084X01(SL) (02)

### LCD Navigation Display For Opel Chevrolet



<b>Model Number</b>	SA1322
<b>Application</b>	Car Navigation
<b>Model</b>	Opel Chevrolet
<b>Part No.</b>	LQ080Y5DZ06/LQ080Y5DZ09/LQ080Y5DZ10 LQ080Y5DZ11/LQ080Y5DZ12

### LCD Display with FPC For DAF LF



<b>Model Number</b>	SA1243
<b>Application</b>	Instrument Cluster
<b>Model</b>	DAF LF (2001-1) / XF 105 (2002-) / XF 95 (2003-), DAF XF 2002 - now, DAF CF 85 (2002-)

### LCD Display with FPC For Fiat Ducato



<b>Model Number</b>	SA1332
<b>Application</b>	Instrument Cluster
<b>Model</b>	Fiat Ducato 3rd-gen; Fiat Ducato LCD Green Version
<b>OE Match</b>	COG-VLIT 1065-11

## The Instrument Cluster LCD Display

### LCD Display with FPC For Mercedes Viano



<b>Model Number</b>	SA1207
<b>Application</b>	Instrument Cluster / Dashboard
<b>Model</b>	Mercedes Viano/Vito/Sprinter (2004+)

### LCD Display with FPC For Fiat 500C Abarth



<b>Model Number</b>	SA1259
<b>Application</b>	Instrument Cluster
<b>Model</b>	Fiat 500C Abarth (2013)
<b>OE Match</b>	COG-VLIT 1592-02

### LCD Display with Pin Connector For BMW 5 Series



<b>Model Number</b>	SA1362
<b>Application</b>	Instrument Cluster / Dashboard
<b>Model</b>	BMW 5 Series E34 instrument clusters (1992 - 1996)

### LCD Display with Pin Connector For Ford Focus



<b>Model Number</b>	SA1365
<b>Application</b>	Instrument Cluster
<b>Model</b>	Ford Focus, C-max (2005-2010)
<b>OE Match</b>	COG-ULUK2181-01

## The Instrument Cluster LCD Display

### LCD Display with Pin Connector For Ford Fiesta



<b>Model Number</b>	SA1310
<b>Application</b>	Instrument Cluster
<b>Model</b>	Ford Fiesta 2013-2017; Ford EcoSport (2013-2017) [PN-1067-02]

### LCD Display with Pin Connector For Renault Clio IV



<b>Model Number</b>	SA1308-1
<b>Application</b>	Instrument Cluster
<b>Model</b>	Renault Clio IV
<b>OE Match</b>	COG-VIST1054-05

## Electronic Actuator for Passenger Vehicle

### SA1130-REA/SREA Gearbox Assembly



<b>Gearbox Part No.</b>	G001-H00HTP-781751, G125-H09-712120-M6, G125-H09-712120-M5, G138-H32-712120, G145-H28-712120, G185-H46-712120, G186-H45-712120, G20-H04H2S-767649
<b>Turbocharger Part No.</b>	887552-1, 781745-1, 761154-5/6/7, 761155-5/6/7, 761156-5/6/7, 770895-5/6/7, 777318-2/3, 781743-1/2/3, 742730-1/2/3/4/5, 750080-50185/4/5/6, 741785-4~9, 750952-4~6/10/12, 742810-7, 742809-7, 742805-5, 750773-7~15, 727461-5, 742693-2, 736088-3, 727463-4, 776470-1/3, 769909-7/9/10
<b>Engine Model</b>	OM642 W2123 3.0LTR, V6 3.7t, M57 TU Euro 3, 2.5d   M57, OM 646.961, OM 611.962, OM 646.962, OM 646.951, OM 646.963, OM 646.966, OM647 DE LA 27, OM647 NAFTA, CDYA CDYC CASA CEZA SASB CCMA CEXA CDYB 3.0L TDI 176kw
<b>Application</b>	Mercedes 3.0, BMW 525D 2.5 530D 2.0 2.9, 2004- BMW 120d 2, 2006- BMW 320d 2, 2003- Volkswagen Touareg 5, 2004- BMW 330d 3.0, 2003-2008 Mercedes C200 / C220 CDI 2.1, 2004- Mercedes C220 CDI 2.2, 2002-2008 Mercedes E200 / E220 CDI 2.1, 2004- Mercedes E200 CDI 2.2, 2002- Mercedes E220 / E220 CDI 2.2, Mercedes GT2256VK 2.2, Mercedes E270 2.7, Mercedes E270 CDI 2.7, 2006-2004 Dodge Sprinter 2500, 2006-2004 Dodge Sprinter 3500, 2006-2004 Freightliner Sprinter 2500, 2006-2004 Freightliner Sprinter 350, 2006 Audi Q7 TDi Quattro 3.0, 2008 Volkswagen Phaeton TDi 3.0, 2008 Volkswagen Touareg TDi 3.0, 2006-2008 Audi Q7 TDi 3.0

### SA1160-IUTA/SUTA -Turbo Actuator



<b>Actuator Part No.</b>	797862-0031/6NW010099-16, 797862-0049/1263E.000181-147, 797862-0056/1263E.000181-186, 797863-0058/6NW010430-25, 797863-0070/6NW010430-24, 797863-0072/6NW010430-29, 797862-0036/6NW010099-22
<b>Turbocharger Part No.</b>	815479-0007~0011, 832453-0002, 870885-0005, 876358-0002/000343259-0003, 1044100FB040, 846108-0002/0003, 873597-0001, 855802-0006, 855862-0001, 821785-2/5, 857039-1, 829440-3, 829440-0003, 829440-5003S, 829440-4, 829440-0004, 829440-5004S, 822182-3/4/6~11/13/14, 848184-0001/0002, 834227-0001/0002,
<b>Engine Model</b>	GW4D20, GW4D20 2.0T 110KW, HFC4DB1-2D 1.9L 102KW Diesel Euro V, Multijet II, TDV6, 3.2 TDCi 4x4, 3.2 TDCi, Duratorq 3.2, 19D4N 1.9 T 110KW Euro V Diesel
<b>Application</b>	XED12: Great Wall 4D20, Garrett GTC14, Turbocharger 1118100XED12, XED15: Great Wall 4D20, Garrett GTC14, Turbocharger 1118100XED15, Jianghuai Ruifeng M4 National V 1.9T, GTD1752V, GTD1449VKZ, LAND ROVER :Discovery V 3.0d, Range Rover V 3.0d, Range Rover Sport II 3.0d, 2016- FORD EVEREST 3.2 d TDCi 2016 ON, 2016- FORD RANGER 3.2 d TDCi 2016 ON, GTC1446 SAIC Maxus G10

### SA1170-CEA Actuator ( connector type 1& type 2& type 3)



	Actuator Part No.	Turbocharger Part No.	Turbocharger Part No.
<b>(connector type 1)</b>	835556-0062		
	835556-0002	Ford -838417-X	Ford MK8 2.0L
	835556-0001	Audi-844437-5	AUDI A8 D5
	835556-0061	Ford -838452-X	Ford MK8 2.0L
<b>(connector type 2)</b>	835556-0020	VW Golf-3777805	VW GOLF VII
<b>(connector type 3)</b>	845780-0001		
	845780-0003	GTD1036KVZ	1.3 MultiJet 95 k E6D
<b>Application</b>	VW 1.5 L, AUDI V6 GEN3 LK3, FORD C/CD CAR TRANSIT MK8 2.0, FIAT 1.3L JTD, MAZDA 2.2L, BMW B47, FOCUS MK4 1.5 TDCI, Minivans & Vans / Motor / FIAT 1.3, DO IVECO DAILY 2.3D F1A 160 113KW 5802377343		

### 800041005-K6T50571- BMW B38/N20- Turbo Actuator



<b>Actuator Part No.</b>	K6T50571
<b>Turbocharger Part No.</b>	11655A14817, 11657633795, 11659895980, 5A14817, 7633795, 9895980
<b>Engine Model</b>	B38 A15A, B38 B15
<b>Application</b>	BMW 116i F20N SH ECE 2R11 B38 03.2015, BMW 118i F20N SH ECE 1R51 B38 07.2015, BMW 116i F21N HC ECE 2P71 B38 03.2015, BMW 118i F21N HC ECE 1P51 B38 07.2015, BMW 218i F22 Cou ECE 2F11 B38 03.2015

### 28230-2F650-Turbo Actuator



<b>Actuator Part No.</b>	59001107605, 59001107220, 59001107607
<b>Turbocharger Part No.</b>	54409880014, A6710900780, 54399880107, 54409700030
<b>Engine Model</b>	D4EAV/D4EAF, D4HA (R-Engine)
<b>Application</b>	BV40/BV43 BorgWarner Turbocharger, Turbo cartridge for Ssangyong Rexton III 2.0XDI D20DTR 2014-2015, Hyundai Santa Fe Tucson Maxcruz Azera Grandeur 2.0 CRDI 2015-



## Electronic Actuator for Commercial Vehicle

### SA1150-HE200VG -Turbo actuator



<b>Actuator Part No.</b>	3778368, 3778364, 5454802, 3778367, 3778369
<b>Turbocharger Part No.</b>	3793016, 5502899, 3792549, 5453459
<b>Engine Model</b>	Cummins ISF2.8 Engine, Cummins QSB Engine, FL912
<b>Application</b>	FOTON AUMARK CUMMINS ISF2.8 2.8L 87KW Euro V Diesel, ISF 2.8 CM2220, TC-5350968, TC-5326247

### SA1150 -HE400/500 -Turbo actuator



Type	Actuator Part No.	Turbocharger Part No.	Engine Model	Application
HE500VG	3787657	4031037H, 3787499, 2191616	DC1305, DLC6	Scania DC1305/ DLC6 EURO5/6
HE500VG	3787658	2191616, 2839392, 3767355	Cummins Engine ISX15, ISX	Scania DLC6/DC1305 engine
HE500VG	3789658	3775775, 21559604, 85020014	Volvo D11, D12, D13, D16 diesel engine	Volvo D11 D12 D13 D16
HE400VG	4046000	3773563, 3773564, 5350504, 2841221	Cummins ISX Engine	Cummins ISX
HE400VG	2837209	HE400VG	Cummins ISX Engine	Cummins ISX
HE400VG	2835944	HE400VG	DAF Paccar	DAF Truck: XF95
HE351VE	3787579	HE531VE 23539570, 23536422, 23536802, 23539062	Detroit Diesel Series 60	2004-14 Daimler Fire Truck, Kenworth, Peterbilt, Freightliner, Various Trucks with 14.0L Detroit Diesel Series 60
HE500VG	2837201	5354714, 5350499, 2882112, 2843821, 2882112NX	Cummins ISX Engine	Cummins ISX15
HE451VE	3791991	5354714, 5350499, 2882112, 2843821, 2882112NX	Cummins ISX15	Cummins ISX15
HE400VG	2837207	85013031, 85013288, 85013597, 21023366	Volvo Engine D13 MP8	Volvo D13/MP8
HE400VG	3787560	3786775, 3791766, 4955401	Cummins ISX Engine	Volvo Cummins ISX HE400VG HE451VE

### SA1150- HE300VG-HE351VE- Turbo actuator



Type	Actuator Part No.	Turbocharger Part No.	Engine Model	Application
HE300 V2	3784299	4309312, 4309312NX, 4352189, 4352189NX, 4352466, 4352466RX, 3798313, 3798313RX, 3775420, 3781727, 3789470, 3796034, 5328174, 3798364, 3798313	Cummins ISB 6.7L engine, ISX ISL ISC	2013-2018 Dodge Ram 2500 3500 ISB 6.7 Cummins
HE300 V2	3784301	3780075		
HE300 V2	5355724	5327132, 5350586, 5351565, 5358003, 5358483, 5358484, 5358485, 5454983, 5454984, 5458937, 5459711, 5358453	Cummins ISX, X15, ISB 6.7L Engine	Cummins X15 2017-2019, Dodge Ram 2500 3500 6.7L 2007-2012, Diesel ISL ISC VGT 300VG 351VE
HE300 V3	3788939	5328296		
HE300 V2	3784300	3789609		
HE300 V1	2837675	3791785	Cummins Engine 6.7L 2007.5-2012	Dodge Ram 2500, 3500, 4500, 5500

### S300V-Turbo Actuator



Actuator Part No.	Turbocharger Part No.	Engine Model	Application
174121	S300V129, S300V110, S300V111, 179035, 175243, 175733, 174121, 179030, 179035, 179036, 175733, 175735, 175243, 173900 28188882, 5010314R94, 5010568R91, 5010569R91, 5010571R91, 5010573R91, 5010581R91, 5010314R95, 1831833C91, 1831835C91 1832204C91, 1832503C91, 1842337C91, 1842582C91, 1850404C95 1870932C91, 1871090C91, 1871092C91	MaxxForce DT466 I313, DT466/570, DT466E/570E Low Mount	2005-12 International Truck, Bus with Navistar MaxxForce DT466 I313 Engine, 2003-08 International Harvester with Navistar DT466/570 Engine
176892	B2BV63, B2UV, B2UV-63A90DR40C12BV-070S71 XA20S78B, B2UV-63A90DR40C12 BV-070S71XA20S78BE, B2UV-63A90DR40C12BV-070S71XA20S78B S, B2UV-63A90DR40C12BV-076S73A118S65BS, B2UV-63A90DR40C12BV-076S73A118S76BE, B2UV-63A90DR40C12BV-076S73AL, BV63-B2V	Navistar-International MaxxForce DT 7.6L 245HP	2005-06 International Truck with 7.6L Navistar MaxxForce DT466 I326 Diesel Engine, 2005-06 International Truck with 9.3L Navistar MaxxForce 9 I326 Diesel Engine, 2005-10 International Truck with 9.3L Navistar MaxxForce DT466/570 I326 Diesel Engine

### SA1192-59001107223 Turbo Actuator



<b>Actuator Part No.</b>	59001107223, 59001107489, 59001107419, 59001107387, 59001107388, 59001107728, 59001107491, 59001107932
<b>Application</b>	International 4300V Turbocharger(2009), GMC CHEVY 6.6L LSP, International Navistar, Ford F250/F350/F450 truck 6.4L power stroke(2008~2010), Dongfeng 1118010-E4600 turbocharger(2014~2019), Chevrolet Silverado GMC Sierra(2010~2014)

### 59001107450-Turbo Actuator



<b>Actuator Part No.</b>	59001107450, 1710200972, C1760036653, 12683983, 12708802
<b>Turbocharger Part No.</b>	1270-970-1044, 1270-970-1050, 1270-970-1026, 11547786, 12683985, 12689094, 12683993
<b>Application</b>	2019 For Chevrolet Silverado 2500 HD High Country, LT, Ltz, WT 6.0L V8-CNG, 6.0L V8-Flex, 6.0L V8-Gas, 6.6L V8-Diesel 2019 For Chevrolet Silverado 3500 HD High Country, LT, Ltz, wt 6.0L v8-cng, 6.0L v8-flex, 6.0L v8-gas, 6.6L v8-diesel

### Hino-Turbo Actuator



<b>Actuator Part No.</b>	726997-0014, 726997-5014, 726997-5014S, 728392-0011, 728392-5011, 728392-5011S
<b>Turbocharger Part No.</b>	GT3576KLV, GT4082KNV
<b>Turbo Type</b>	REA/VNT, DC24V
<b>Engine Model</b>	Hino J07E, J08E
<b>Application</b>	Toyota, Hino with J08E Engine, 2005- Hino Ranger Truck with J07E Engine